

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:									
Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Martin		
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		PERMIT NO.: SLAS-59-02		
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		FILE TYPE: COMPLIANCE		

Date of Site Inspection: $\underline{11/16/2012}$ **Date of Last Inspection:** $\underline{8/9/2012}$

FACILITY NAME AND ADDRESS:

Russ Ayers Bennie A. Moore Septic Tank Service Inc. 4294 US Hwy 17 South Williamston, NC 27892

GPS COORDINATES: <u>N</u>: 35.79046 <u>W</u>: -77.09433

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Russ Ayers

Telephone: 252-792-5978

Email address: bmoore4294@aol.com

Fax: 252-792-1074

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: Chester Cobb

STATUS OF PERMIT: Active EXPIRES: 4/16/2015

PURPOSE OF SITE VISIT: Routine

STATUS OF PAST NOTED VIOLATIONS:

No violations noted from the previous inspection coducted on 8/9/12.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. Signage present along access path to site.
- 2. Access path was in excellent shape.
- 3. Field markers present.
- 4. No discharges noticed outside of the permitted boundaries.
- 5. No spot dumps or thick applications noted.
- 6. Rye had been overseed into the bermudagrass fields and was up. Field 6 had been replanted in fescue.
- 7. No application at time of inspection. pH not checked.
- 8. No objectionable odors noticed.
- 9. No issuses noticed with setbacks.
- 10. Records not checked.
- 11. Soil samples were collected from the fields. No violations noticed today.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Regional Representative

Phone: (919) 707-8283

Sent on: 7/25/13 Email Hand delivery X US Mail	Certified No. [_]
--	-------------------